

APPENDIX 22

Potentially impacted trees along culvert routes (Part B Works)

Option 3A

	Structural root zone impacted trees			
	No. trees	Significant	Regulated	Other
Jervois Street	2	1	1	-
Hampton Street	20	-	6	14
Hilda Terrace	-	-	-	-
Wurilba Avenue	31	4	3	24
Malcolm Street (west)	23	-	-	23
Vardon Terrace	40	1	-	39
Arundel Avenue	60	-	7	53
Nanthea Tce. North	49	10	9	30
Nanthea Tce. South	6	-	-	6
Totals	231	16	26	189
Total trees assessed	455			

Option 3

	Structural root zone impacted trees			
	No. trees	Significant	Regulated	Other
Jervois Street	2	1	1	-
Grove Street	18	1	1	16
Northgate Street	8	-	-	8
Wood Street	10	-	-	10
Malcolm Street (east)	11	2	4	5
Malcolm Street (west)	23	-	-	23
Vardon Terrace	40	1	-	39
Arundel Avenue	60	-	7	53
Totals	172	5	13	154
Total trees assessed	298			

Dam option

	Structural root zone impacted trees			
	No. trees	Significant	Regulated	Other
Malcolm Street (west)	23	-	-	23
Vardon Terrace	40	1	-	39
Arundel Avenue	60	-	7	53
Totals	123	1	7	115
Total trees assessed	194			